

Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 9/1/2023



Inspection Photos



Photo 1. Facing southeast toward the abandoned wellsite which was never reclaimed. Soils remain bare of vegetation..



Inspection Photos



Photo 2. There is a cement block that remains at the east side of the location that needs to be removed.



Inspection Photos



Photo 3. Facing southeast at the east side of the location. Another cement block remains and a metal pipe anchor shown at red arrow..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing northeast at the wellsite. There is a metal cable guyline anchor that remains at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources