

Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 9/1/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the abandoned wellsite which was never reclaimed. Soils remain bare of vegetation and there is erosion occurring.



Inspection Photos



Photo 2. Facing southeast at the location. Soils remain bare of vegetation and reclamation was never performed.



Inspection Photos



Photo 3. Facing south at the location. There is metal cable and pipe that remains along with other debris.



Inspection Photos



Photo 4. Facing southeast. There is a degraded perimeter fence that remains around the location. There is also an old bridge timber that remains.



Inspection Photos



Photo 5. Facing northwest at the location. Soils remain bare of vegetation and reclamation was never performed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-40000 | Date: 9/1/2023

Inspection Photos



Photo 6. Facing northwest at the wellsite. There is an abandoned powerpole that has not been removed

