

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 8185 From entrance to location



Photo # 8186 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 8187 Location



Photo # 8188 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 8196 Location



Photo # 8197 RWF 413-16 wellhead sign weathered/cracking & some info illegible

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 8189 Open ended load line



Photo # 8199 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188



Photo # 8200 Debris



Photo # 8201 Debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC LANGSTAFF RMV 12-16 Pad

Location # 335188




Photo # 8205 Debris



Photo # 8206 Debris