

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 8/24/2023



NE Corner of Location – Photo #06131



SE Corner of Location – Photo #06132

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 8/24/2023



SW Corner of Location – Photo #06133



Wellhead – Photo #06137

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 8/24/2023



Separator – Photo #06138



Tank Battery – Photo #06139

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 8/24/2023



Location Lacks Stabilization – Photo #06134

Location Lacks Stabilization – Photo #06136

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 8/24/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06141**

Access Road Degradation – Photo #06142

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWNE

Location ID: 323960

Date: 8/24/2023



**Access Road Degradation/Insufficient Erosion Control –
Photo #06144**

Insufficient Erosion Control/Rill Erosion – Photo #06146