

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 8/24/2023



SW Corner of Location – Photo #06158



Wellheads – Photo #06160

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 8/24/2023



Separators – Photo #06165



Tank Battery – Photo #06164

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 8/24/2023



Location Lacks Stabilization – Photo #06159



Location Lacks Stabilization – Photo #06161

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 8/24/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06163**



**Insufficient Erosion Control/Rill Erosion on Access Road –
Photo #06166**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWSE

Location ID: 334870

Date: 8/24/2023



**Insufficient Erosion Control/Rill Erosion on Access Road –
Photo #06168**



Check Dam BMP Needs Maintenance – Photo #06169