

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESW

Location ID: 335420

Date: 8/28/2023



West Entrance to Location – Photo #06208



SE Corner of Location – Photo #06209

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESW

Location ID: 335420

Date: 8/28/2023



Wellheads – Photo #06210



Separators – Photo #06212

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESW

Location ID: 335420

Date: 8/28/2023



Tank Battery – Photo #06211



Location Lacks Stabilization – Photo #06213

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20NESW

Location ID: 335420

Date: 8/28/2023



Location Lacks Stabilization – Photo #06215



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06216