

**Inspection Photos**  
**Location Name: Turner #1**  
**API: 05-067-05316**



**Turner #1 pumping unit.**



**Open excavation around well head.**



**Inspection Photos**  
**Location Name: Turner #1**  
**API: 05-067-05316**



**Open excavation around well head.**



**Electrical wires have been severed at the power pole.**