

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2023

Submitted Date:

08/29/2023

Document Number:

704900014**FIELD INSPECTION FORM**Loc ID 312681 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 5525 N UNION BLVD #200City: COLORADO State: CO Zip: 80918**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

**General Comment:**

On 8/25/23 ECMC OWP Western EPS Jim Hughes conducted a field inspection of the Fram Operating LLC Federal (OWP) #12-2. For the most recent field inspection report of this facility, please refer to Document #693801098.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt access road with locked gate.		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
<p>On 8/25/23 ECMC OWP Western EPS Jim Hughes conducted a field inspection of the Fram Operating LLC Federal (OWP) #12-2. For the most recent field inspection report of this facility, please refer to Document #693801098.</p> <p>This inspection was conducted to determine the status of this facility for the OWP. The well/facility appears to have been decommissioned since the last inspection. There is not a Form 6 Subsequent in well file. Form 6 Initial (Doc. #1310178) was received on 9/2/20. This document was submitted by Everton Operating LLC, operator #28035.</p> <p>No PA marker was observed during this inspection.</p> <p>Location appears to have been reclaimed. Cut and fill slopes are still apparent.</p> <p>Locked gate along access road.</p>	hughesjo	08/29/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
704900015	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242261">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242261</a>