

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

08/31/2023

Document Number:

704900022

FIELD INSPECTION FORM

 Loc ID 325511 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10254

Name of Operator: RED MESA HOLDINGS/O&G LLC

Address: 5619 DTC PARKWAY - STE 800

City: GREENWOOD State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 214922 | WELL | PR | 09/30/2010 | GW | 067-06526 | HERRERA (OWP) 3 | EI |

General Comment:

On July 19, 2023 ECMC OWP West EPS Jim Hughes conducted a field inspection of the Red Mesa Holdings Herrera #3. For the most recent field inspection report of this facility, please refer to document #685304183.

| Location | | | |
|--------------------------------------------------------|--------------------------------------------------------------------|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt access road also serves as the driveway for nearby residence. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal sign mounted to guard fencing for pumping unit. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Labels and NFPA placards on tanks. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | COGCC emergency contact sticker on wellhead sign. | | Date: _____ |
| Corrective Action: | | | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Wire fence. | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Guard fencing. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Domestic tap. Steel barricade. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Gas Meter Run | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------------------------|-------|--|
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric supply panels. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLs | STEEL AST | | 37.080664,-108.119287 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | | | Date: |

Wells Served By Facilities Above

| API Number |
|------------|
| 067-06776 |
| 067-06632 |
| 067-06526 |

AirsID

| API Number | AirsID |
|------------|--------|
| | |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 214922 Type: WELL API Number: 067-06526 Status: PR Insp. Status: EI**COGCC Comments**

| Comment | User | Date |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|
| On July 19, 2023 ECMC OWP West EPS Jim Hughes conducted a field inspection of the Red Mesa Holdings Herrera #3. For the most recent field inspection report of this facility, please refer to document #685304183. This site visit was performed with Cottonwood Consulting representatives to assess current conditions at this facility prior to plugging and abandonment. | hughesjo | 08/31/2023 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 704900023 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242266 |