

Location

Overall Good:

Signs/Marker:			
Type			
Comment:	No TB or WH signs		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	606 tall undesirable vegetation throughout location		
Corrective Action:			Date:
Type	OTHER		
Comment:	608 Mechanical Issue, Well head is leaking		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		39.866840,-104.396800

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-07615		

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202210 Type: WELL API Number: 001-07615 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/03/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Complaint

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 39.866840 Long: -104.396800

Wind: Light Speed: 1-2 (mph) Direction From: w Weather: Cloudy Temperature: 82 (F)

Assisting Staff: _____ Camera #: _____

Visible Smoke Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
0316	PM	0317	PM	Wellhead(s)

Comment: _____

Corrective Action: _____

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 8-28-2023 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: OWP/Painted Pegasus Petroleum Location name: Antelope Farms 41-23 (OWP)2 API #05-001-07615 County: Adams Weather: Clear, Sunny. Location: Dry. While there, I observed a wellsite and tank battery, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 606 housekeeping: 608 Mechanical Issue: 605 signs: See attached photos and video. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402289	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242441
702402290	FLIR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242442