

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chainlink		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	chainlink		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	chainlink		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment: card indicates current calibration		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 5	
Comment: automation		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: exposed at surface		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	75 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: shares containment with crude tank				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		40.168470,-104.964760
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	335 bbl

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Wells Served By Facilities Above

API Number
123-21690

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 269523 Type: WELL API Number: 123-21690 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 18 Fluid Type: WATER H2O

End Surf Csg Pressure: 1

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 8-29-2023 at approximately 1430 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location name: BLC 8-28 API #05-123-21690 County: Weld Weather: Clear, Sunny. Location: Dry. While there, I observed a wellsite and tank battery, PR at the time of the inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	08/29/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402302	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242448