

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2023

Submitted Date:

09/06/2023

Document Number:

707601792

**FIELD INSPECTION FORM**

Loc ID 302630 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414607	WELL	TA	10/01/2019	GW	123-30789	THISTLE DOWN B 31-22D	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Plugging Operations: Cementing: Cement-surface.  
Battery: Inactive. Shut-down.  
Inactive Battery SE corner GPS coordinates: 40.355963 / -104.593403  
Well GPS coordinates: 40.356256 / -104.592423

**Location**

**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 414607 Type: WELL API Number: 123-30789 Status: TA Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Axis Energy Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 729'-0' Cement Volume (sx): 298 sxs

Good Return During Job: YES Cement Type: Class "G" Neat 15.8#

Comment: [Workover Contractor: Axis Energy Services, Rig #726.](#)  
[Cement Contractor: Axis Energy Services.](#)

Reference:  
[Form 6N on file. Notice of Intent to Abandon date: 07/13/2023. Approved.](#)  
[Form 42 on file. Notice of MIRU. Start Date: 08/29/2023. Approved.](#)  
[Form 42 on file. Notice of Plugging Operations. Start Date: 08/29/2023. Approved.](#)

2023/09/05:  
[Plugging Operations: Cementing: Initial plug\(s\).](#)  
[2023/09/05: JSA attached as photo to this report.](#)

**SAFETY MEETING**  
 SI BH 0PSI  
 SAFETY STAND DOWN AT AXIS YARD. JSA MEETING. CHECK PRESSURES. LOAD WELL W/ 8BBLS OF FRESH. 30MIN FLOW CHECK, NO FLOW/NO PSI BUILD UP. SWC/SYLA ON WORKING AT HEIGHTS AND TUBULAR'S. TIH47JTS OF 2.375" J55 4.7# TBG TAG TOC @ 1,435.0'. PUH TO 729.0' W/ 24JTS. JSA MEETING W/ RIG CREW AND CMT HANDS, MIRU AXIS CMT, BREAK CIRC, PUMP10BBLS OF M/F, 5 BBL SPACER, MIX AND PUMP298SKS (61BBLS) OF CLASS G NEAT 1.15YLD 15.8# CMT TO SURFACE, CMT IN RETURNS. TOOH, LD TBG. TOP WELL OFF W/ CMT. CLEAN EQUIP AND TANKS. SWC/SYLA ON WORKING AT HEIGHTS AND LIFTING AND RIGGING. RD RIG FLOOR AND EQUIP. ND BOPS AND P&A SPOOL. INSTALL SCSG CAP. SWC/SYLA ON LIFTING AND RIGGING. RD AXIS726.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/> <span style="float: right;">Date: _____</span>						
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On TUE 09/05/2023 at approximately 12:54 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: THISTLE DOWN B/31-20D                      Location ID: 302630                      Well Name(s):                      Thistle Down B 31-22D.                      API: 123-30789.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Cementing: Cement-surface.                      Battery: Inactive. Shut-down.                      Inactive Battery SE corner GPS coordinates: 40.355963 / -104.593403                      Well GPS coordinates: 40.356256 / -104.592423</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/06/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601793	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242578">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242578</a>