

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2023

Submitted Date:

09/06/2023

Document Number:

712700614

FIELD INSPECTION FORM

Loc ID 326585 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258308	WELL	PR	08/01/2018	CBM	067-08351	LE PLATT A 2	PR

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location			
Lease Road:			
Type	Access		
comment:	Locked gate, 2C40 key.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Placards and signs on separator, meterhouse, and sound abatement wall.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on wellhead sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Undesirable vegetation (Kochia) growing on location.		
Corrective Action:	Remove undesirable vegetation across location per Rule 606.C.		Date: 09/12/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Telemetry enclosed by cattle panel.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Separator and meterhouse enclosed by cattle panel.		
Corrective Action:			Date:
Type	LOCATION		
Comment:	T-post and barbed wire.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sound abatement walls and cattle panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electrical service box and panel.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	2" line from wellhead to separator.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to meterhouse. Calibration date 8/9/2023.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 258308 Type: WELL API Number: 067-08351 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass			
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Location adjacent to large, flowing irrigation canal.
No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700619	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6243275