

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/31/2023

Document Number:

713600146

**FIELD INSPECTION FORM**Loc ID 324823 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BEAR STACY		stacy@strachanexploration.com	
HARMS JASON		jason@strachanexploration.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212935	WELL	PR	05/01/2021	GW	061-06296	FRAZEE 1-6	RI

**General Comment:**

On 8/24/2023, Ryan Costa conducted a follow up location inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: The oily fluid and sludge at the pumpjack was cleaned up.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type TANK BATTERY

Comment: The fence around the tank battery is inadequate to prevent livestock entry and is not maintained. Corrective action will remain out of compliance until completed.

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 06/29/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		Open Top		,

Comment: Netting appeared to be fixed.

Corrective Action:

Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate			

Comment: The berm at the open top tank is inadequate to contain a spill as it is piled up against the tank and would spill over the berm along this side. Corrective action will remain out of compliance until completed.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 06/29/2023

**Venting:**

Yes/No

Comment:

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403516931	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238226</a>
713600147	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6238212</a>