

# Inspection Photos

API: 011-06024

Operator: OXY USA INC

Inspection Date: 9/6/2023



## Inspection Photos



**Photo 1.** Facing west at the location. This area approx. 200'x30' has not re-established perennial vegetation.





## Inspection Photos



**Photo 2.** Facing east at the location. This area approx. 200'x30' has not re-established perennial vegetation.





## Inspection Photos



**Photo 3.** South side of the location facing. The turn around area of the road has not re-established perennial vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** North side o the location facing southwest. This area that was reclaimed and stabilized with straw blanket has re-established perennial vegetation..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources