

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2023

Submitted Date:

09/07/2023

Document Number:

708901581

**FIELD INSPECTION FORM**

Loc ID 335251 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

18 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211234	WELL	PR	09/19/1995	GW	045-06993	CLOUGH RMV 55-20	PR
211362	WELL	PR	08/09/1997	GW	045-07122	RMV 201-20	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 09/07/2023 at approximately 10:26 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 55-20 Pad. Location # 335251 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. Location is approximately 80 yards from a creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

This is a summary of inspection report.

Split pad/Remote location - 3 wells associated with this this pad are located on the RMV 58-20 pad, location # 335135.

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:	RMV 201-20 pipe rail fence RMV 55-20 pipe rail fence & hog panels		
Corrective Action:			Date:
	Type TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 5		
Comment:	Marked		
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	RMV 55-20 well has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.  RMV 201-20 well has Taylor plug located on bradenhead, bradenhead valve is accessible. Bradenhead line is connected to flowline.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

<b>Paint</b>				
Condition	Adequate			
Other (Content)				
Other (Capacity)	80 bbl			
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 211234 Type: WELL API Number: 045-06993 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 211362 Type: WELL API Number: 045-07122 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Retention Ponds				
Gravel						Sparse in most areas
		Culverts				
		Compaction				
		Gravel				Sparse in areas
Compaction						Light compaction

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Split pad/Remote location - 3 wells associated with this this pad are located on the RMV 58-20 pad, location # 335135.</a>	smelserw	09/07/2023
<a href="#">Remote location is within the Garfield County Landfill.</a>		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901583	Inspection 708901581 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245033</a>
708901584	Inspection 708901581 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245034</a>