

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2023

Submitted Date:

08/24/2023

Document Number:

694500588

**FIELD INSPECTION FORM**

Loc ID 324641 Inspector Name: NEIDEL, KRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 34162  
Name of Operator: GILS HOT OIL SERVICE  
Address: P O BOX 418  
City: STRASBURG State: CO Zip: 80136

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ramsey, Scott		scott.ramsey@state.co.us	
Paine, Gilbert	303709-0148	cherokeeequipment@hotmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212246	WELL	PR	05/01/2021	OW	057-06139	STATE 5	EI

**General Comment:**

Any Corrective Actions from previous Inspections that have not been addressed are still applicable. On 8/3/23, C-ECMC staff, Kris Neidel was on location to inspect the State 5 Well. The well was SI at the time of inspection. The following was observed. Pumping unit on a ground with one end on wood. Well has a wired up pump rod as a fence. Flowlines: there is a shallow buried line from the wellhead to tank, There is a 200bbl tank that has NO secondary containment. The soil at the tank battery is Sand. Lack of secondary containment was documented on Inspection 707800362, 5/12/23 and inspection going back to at least 2011, doc 200325508. See attached Photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLs	STEEL AST		,

Comment: Secondary containment is insufficient

Corrective Action: Repair or install berms or other secondary containment devices

Date: 06/23/2023

Paint

Condition:

Other (Content):

Other (Capacity):

Other (Type):

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate

Comment: Secondary containment is insufficient

Corrective Action: Repair or install berms or other secondary containment devices

Date: 06/23/2023

**Venting:**

Yes/No:

Comment:

Corrective Action:

Date:

**Flaring:**

Type: <input type="text"/>	
Comment: <input type="text"/>	
Corrective Action: <input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 212246 Type: WELL API Number: 057-06139 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403518801	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239933</a>
694500589	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239927</a>