

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2023

Submitted Date:

09/07/2023

Document Number:

705000420

FIELD INSPECTION FORM

Loc ID 327357 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246757	WELL	SI	05/24/2023	GW	123-14554	BRIGGS AGGREGATE 1-25	PA
327357	LOCATION	AC			-	BRIGGS AGGREGATE-61N67W 25SESW	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photo uploaded

Inspected FacilitiesFacility ID: 246757 Type: WELL API Number: 123-14554 Status: SI Insp. Status: PA**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well (Briggs Aggregate 1-25) is plugged and abandoned. COGCC form 42 notice of start of plugging operations doc #403463650 received 07/13/2023. The OL WH FL has been removed; COGCC form 42 flowline pre-abandonment notice doc #403396650 received 05/10/2023. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines are removed (in progress). An open excavation observed at facility/ equipment (HHS) area; remediation work is in progress.

Corrective Action:

Date:

Facility ID: 327357 Type: LOCATION API Number: - Status: AC Insp. Status: EG**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403517890 received on 08/31/2023: On Location Flowline; A historic release was discovered near the separator.	maclarej	09/07/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000421	Signage at lease road	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245469
705000422	Flowline pipe removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245470
705000423	Excavation at HHS; work in progress	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245472