

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2023

Submitted Date:

09/08/2023

Document Number:

707601807

**FIELD INSPECTION FORM**

Loc ID 302630 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414633	WELL	TA	07/01/2019	GW	123-30806	THISTLE DOWN B 31-18D	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Plugging Operations: Cementing: Cement-surface.  
Battery: Inactive. Shut-down.  
Inactive Battery SE corner GPS coordinates: 40.355963 / -104.593403  
Well GPS coordinates: 40.356254 / -104.592529

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type OTHER		
	Comment: Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment:		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:		
	<input style="width: 90%;" type="text"/>		
Corrective Action:	<input style="width: 90%;" type="text"/>		Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 414633 Type: WELL API Number: 123-30806 Status: TA Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Axis Energy

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 0'

Cement Volume (sx): 283 sxs

Good Return During Job: YES

Cement Type: Class "G" Neat 15.8#

Comment: [Workover Contractor: Axis Energy Services, Rig #726.](#)  
[Cement Contractor: Axis Energy Services.](#)

Reference:  
[Form 6N on file. Notice of Intent to Abandon date: 07/13/2023. Approved.](#)  
[Form 42 on file. Notice of MIRU. Start Date: 09/06/2023. Approved.](#)  
[Form 42 on file. Notice of Plugging Operations. Start Date: 09/06/2023. Approved.](#)

2023/09/07:  
[Plugging Operations: Cementing: Cement-surface.](#)  
[2023/09/07: JSA attached as photo to this report.](#)

**SAFETY MEETING**  
 SI CSG 0PSI  
 SI BH 0PSI  
 WSR MEETING. JSA MEETING, CHECK PRESSURES. 30MIN FLOW CHECK, NO FLOW / NO PIS. JSA MEETING W/ RIG CREW AND CMT HANDS. MIRU AXIS CMT, SWC/SYLA ON LIFTING AND RIGGING. BREAK CIRC. PUMP 5BBLS OF FRESH, MIX AND PUMP 283SKS (58BBLS) OF CLASS G NEAT 1.15YLD 15.8# CMT TO SURFACE, CMT IN RETURNS. CLEAN OUT WORK TANKS. RD FLOWLINES. RDMO.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On THU 09/07/2023 at approximately 09:55 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: THISTLE DOWN B/31-20D                      Location ID: 302630                      Well Name(s):                      Thistle Down B 31-18D.                      API: 123-30806.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Plugged &amp; Abandoned   PA.                      Plugging Operations: Cementing: Cement-surface.                      Battery: Inactive. Shut-down.                      Inactive Battery SE corner GPS coordinates: 40.355963 / -104.593403                      Well GPS coordinates: 40.356254 / -104.592529</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/08/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601808	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245889">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245889</a>