

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2023

Submitted Date:

09/08/2023

Document Number:

705000425

FIELD INSPECTION FORM

Loc ID 321359 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5200
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
McQueen, Costin		cmcqueen@civiresources.com	
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206768	WELL	PR	06/01/2023	GW	013-06263	BRERETON 2-14	PA
321359	LOCATION	AC			-	BRERETON-61S69W 14SWSE	EG

General Comment:

ECMC follow up inspection (EG) conducted on 9/07/23. The Corrective Actions outlined on FIR Doc #705000412 submitted on 08/29/2023 have been completed. Details are outlined in the flowline and comment sections of this report. Photos Uploaded.

Inspected Facilities

Facility ID: 206768 Type: WELL API Number: 013-06263 Status: PR Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Corrective actions as outlined have been completed; OOSLAT (tags) applied to Brereton 2-14 on location wellhead flowline at PA well and inlet to heated horizontal separator meet 1105.b.

*Note: A liquid filled pressure gauge has been installed on Brereton 2-14 OL WH flowline at the flowline manifold inlet to HHS. This is being deemed an acceptable pressure monitoring method to meet 1105.c until the flowline is permanently removed.

Corrective Action:

Date:

Facility ID: 321359 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
ECMC FIRR Doc #403520688 recieved on 9/5/2023 and ECMC FIRR Doc #403520690 recieved on 9/6/2023 have been approved/ passed.	maclarej	09/08/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000426	Signage at lease road	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245983
705000427	OOSLAT on flowline valve; PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245984
705000428	OOSLAT on flowline valve at HHS; pressure gauge	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245986