

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



**Location Overview: Location is within High Priority/Density
Habitat Areas.**

Section/Township/Range: 15 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



Photo # 8331 Erosion & transport of sediment off location & into a vegetated area/BMP's need maintenance



Photo # 8335 Erosion & transport of sediment off location & into a vegetated area

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



Photo # 8336 Erosion & transport of sediment off location & into a vegetated area



Photo # 8340 Erosion & transport of sediment off location & into a vegetated area/BMP's need maintenance

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



Photo # 8341 Erosion & transport of sediment off location & into a vegetated area/BMP's need maintenance



Photo # 8342 Erosion & transport of sediment off location & into a vegetated area

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



Photo # 8344 Erosion & transport of sediment off location & into a vegetated area



Photo # 8362 Rip Rap/BMP's need maintenance/erosion & transport of sediment/insufficient runoff controls/BMP's (NW corner of location after sediment trap)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



Photo # 8363 Rip Rap/BMP's need maintenance/erosion & transport of sediment/insufficient runoff controls/BMP's (NW corner of location after sediment trap)



Photo # 8364 Rip Rap/BMP's need maintenance/erosion & transport of sediment/insufficient runoff controls/BMP's (NW corner of location after sediment trap)

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad
Location # 335572



Photo # 8365 Rip Rap/BMP's need maintenance/erosion & transport of sediment/insufficient runoff controls/BMP's (NW corner of location after sediment trap)



Photo # 8368 Rip Rap/BMP's need maintenance/erosion & transport of sediment/insufficient runoff controls/BMP's (NW corner of location after sediment trap)