

Inspection Photos
Location Name: Doris Ackerson Unit 4
Location ID: 318638



Photo 1 well head and equipment



Photo 2 well sign

Inspection Photos
Location Name: Doris Ackerson Unit 4
Location ID: 318638



Photo 3 debris on site



Photo 4 electrical panel and debris

Inspection Photos
Location Name: Doris Ackerson Unit 4
Location ID: 318638




Photo 5 equipment and debris