

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/24/2023

Document Number:

713300040

**FIELD INSPECTION FORM**Loc ID 317675 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
, KPK		cogcc@kpk.com	All inspections
Silver, Randy		randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239762	WELL	PR	01/01/2022	OW	123-07550	JAMES H MATHISEN UNIT 1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) Sign is missing 911		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	09/25/2023

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	overgrown vegetation		
Corrective Action:	Comply with Rule 606	Date:	09/25/2023
Type	STORAGE OF SUPL		
Comment:	land owners storge of supplies and equipment is blocking access to well.		
Corrective Action:	Comply with Rule 606	Date:	09/25/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 239762 Type: WELL API Number: 123-07550 Status: PR Insp. Status: PR**Producing Well**Comment: PR At time of inspection it appears the flowline valves are in the closed position.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 06/26/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

ECMC Inspection Report Summary  
 On Thursday, 8-24-23 at approximately 10:30, I, Inspector Michael Kester, conducted an on-site inspection.  
 Location: James H Mathisen Unit 1  
 Operator: KPK  
 API#: 123-07550  
 County: Weld  
 While there, I observed well that appeared to be shut-in  
 During this inspection the following possible compliance issues were observed:  
 Weeds, Rule 606, corrective action date 9-25-2023, see photos 1, 3, 4, & 5  
 Storage, Rule 606, corrective action date 9-25-2023 see photos 1,3, 4, & 5  
 Contact phone numbers, Rule 605d, corrective date 9-25-2023  
 Weather conditions: Dry & Sunny  
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.  
 This is a summary of inspection report.

kesterm

08/24/2023

This inspection does not nullify any orders or NOAV from the COGCC

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
713300041	Site pic	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247241">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247241</a>