

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/24/2023

Document Number:

713300044

FIELD INSPECTION FORMLoc ID 317690 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Silver, Randy		randy.silver@state.co.us	
, KPK		cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239790	WELL	SI	04/01/2023	GW	123-07578	DORIS ACKERSON UNIT 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	"Sign not legible Sign not updated to reflect current operator"		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/25/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	overgrown vegetation		
Corrective Action:	comply with Rule 606	Date:	09/25/2023

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical panel		
Corrective Action:		Date:	

Venting:

Yes/No NO

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 239790 Type: WELL API Number: 123-07578 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: at time of inspection flow line valves appeared to be in the closed position.Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 03/01/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday, 8-24-23 at approximately 12:00, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Doris Ackerson Unit 1</p> <p>Operator: KPK</p> <p>API#: 123-07578</p> <p>County: Weld</p> <p>While there, I observed a well that appeared to be shut-in</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds, Rule 606, corrective action date 9-25-2023, see photos 1, 2, 3, & 4</p> <p>Sign Faded, Rule 605g, corrective action date 9-25-2023 see photo 2</p> <p>Weather conditions: Dry & Sunny</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	08/24/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300045	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247244