

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2023

Submitted Date:

09/11/2023

Document Number:

697504822

**FIELD INSPECTION FORM**Loc ID 332308 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		Austin_Lee@oxy.com	
		Anthony_Rader@oxy.com	
		COGCCInspections@Oxy.com	All inspections
		lynna_scranton@oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271768	WELL	SI	12/01/2020	GW	123-22120	CROISSANT 30-13	RI

**General Comment:**

On 8/23/2023, Reclamation Specialist Chris Binschus performed a follow up inspection to Field Inspection Report Doc.# 697504777.

Note- Due to ECMC database migration, this inspection is being resubmitted as the original Field Inspection Report Doc.# 697504805 never submitted.

**Location****Lease Road:**

Type	Main		
comment:	<p>At the time the original Field Inspection Report was submitted back on August 24, 2023, Operator representatives continued to use an unauthorized route, as documented by the surface owner, and have not provided Operator correspondence regarding the proper route is utilized.</p> <p>On 8/30/2023, Operator submitted FIRR Doc.# 403515938 providing Operator correspondence documentation with a map instructing contractors and Operator representatives about the proper traffic route.</p> <p>On 9/11/2023, ECMC approved the documentation instructing contractors and Operator representatives about the proper route.</p>		
Corrective Action	L	Date:	
Type	Main		
comment:	<p>At the time the original Field Inspection Report was submitted back on August 24, 2023, Operator representatives continued to use an unauthorized route, as documented by the surface owner, and have not implemented any BMPs to ensure the proper route is utilized.</p> <p>On 8/30/2023, Operator submitted FIRR Doc.# 403515938 documenting that two "No Oilfield Traffic" signs have been installed to prevent vehicle traffic along the western portion of the lake.</p> <p>On 9/11/2023, ECMC approved pending re-inspection regarding robust best management practices to ensure the proper route is utilized.</p>		
Corrective Action	L	Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Operator performed the corrective action to remove unmanaged weeds per Rule 1003.f.		
Corrective Action:			Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--



**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: [ECMC staff has observed Operator communication to the surface owner about the need to submit a variance request for the access road to remain after plugging and abandonment. A variance request would not be needed, as the access road in question was built specifically for DRMS mining operations, not for oil and gas operations. Oil and gas does share that road but that road is to remain per the DRMS mining operations Reclamation Plan. Refer to Photos 3-5.](#)

Inspector Name: Binschus, Chris

Corrective Action:		Date	
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>

**COGCC Comments**

Comment	User	Date
Note- Due to ECMC database migration, this inspection is being resubmitted as the original Field Inspection Report Doc.# 697504805 never submitted.	binschusc	09/11/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697504823	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247512</a>