

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



West End of Location – Photo #06252



Wellhead – Photo #06253

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



Separator/Gas Meter Run – Photo #06255



Tank Battery – Photo #06254

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



Rill Erosion Transporting Sediment Off-Location – Photo #06258



Rill Erosion Transporting Sediment Off-Location – Photo #06259

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



Gulley Erosion Transporting Sediment Off-Location – Photo #06261



Location Lacks Stabilization – Photo #06263

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



**Rill Erosion Transporting Sediment from Access
Road to Drainage Ditch – Photo #06265**



**Rill Erosion Transporting Sediment from Access
Road to Drainage Ditch – Photo #06267**

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



Access Road Lacks Stabilization – Photo #06269



Access Road Lacks Stabilization – Photo #06270

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 324270

Date: 9/6/2023



Insufficient Vehicle Tracking BMPs at Location

Entrance/Exit – Photo #06271