

Inspection Photos

API: 011-06046

Operator: STRACHAN EXPLORATION INC

Inspection Date: 9/6/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west along the former access road. There are areas of the road that have not established vegetation.



Inspection Photos



Photo 2. Facing west toward the location which has not been reclaimed. There are undesirable weeds throughout the location and areas bare vegetation. There is equipment that remains at the north side of the location. Previous corrective action was not completed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-06046 | Date: 9/6/2023

Inspection Photos



Photo 3. There are pipe risers associated with the former well site that have not been removed. Previous corrective action was not completed.



Inspection Photos



Photo 4. North side o the location facing east. There are areas of the location that are bare of vegetation or consist of undesirable weeds.



Inspection Photos



Photo 5. South side of the location facing north. There are undesirable weeds throughout the location and areas bare vegetation. Reclamation has not been completed.



Inspection Photos



Photo 6. Facing south at the surrounding undisturbed reference area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.

