

Inspection Photos

API: 011-06108

Operator: THOMAS L SPRING LLC

Inspection Date: 9/6/2023



Inspection Photos



Photo 1. Facing west toward the abandoned wellsite. There is an abandoned pipe riser that still remains at the location. .

