

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2023

Submitted Date:

09/12/2023

Document Number:

701103811

FIELD INSPECTION FORMLoc ID 314460 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Sanford, Anita	(970) 675-3842	Anita.Sanford@scoutep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228763	WELL	AC	05/01/2023	OBW	103-05743	HAGOOD A-2	EG

General Comment:

Flowline integrity inspection

Inspected FacilitiesFacility ID: 228763 Type: WELL API Number: 103-05743 Status: AC Insp. Status: EG**Flowline**

#1	Type:	1 of Lines
----	-------	------------

Flowline Description

Flowline Type: Size: 2" Material: Carbon Steel
Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Temporary Flowline for blowing down Hagood LN A2 production casing and drop BHP before repairs. Line to be removed no later than October 31, 2023. Line is running from A2 to Haggod LN A10X (05-103-07913)

Corrective Action: Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103812	Flowline integrity inspection 701103811 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248641
701103813	Scout Energy Temporary FFlowline Plan A2 to A10X	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248642