

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/31/2023

Submitted Date:

09/12/2023

Document Number:

701103814

FIELD INSPECTION FORM
 Loc ID 316361 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|----------------|-------------------------------|---------------------------------|
| Sanford, Anita | (970) 675-3842 | Anita.Sanford@scoutep.com | All Inspections |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Regulatory, Rangely | | RangelyRegulatory@scoutep.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 269153 | WELL | PR | 01/01/2020 | OW | 103-10365 | FEE 154X | EG |

General Comment:[Flowline integrity inspection](#)

Inspected FacilitiesFacility ID: 269153 Type: WELL API Number: 103-10365 Status: PR Insp. Status: EG**Flowline**

| | | |
|----|-------|------------|
| #1 | Type: | 1 of Lines |
|----|-------|------------|

Flowline Description

Flowline Type: Size: Material: Carbon Steel
Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Temporary flowline from Gray B4 (05-103-06133) to Fee 154X has been removed.

Corrective Action: Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 701103815 | Flowline integrity inspection 701103814 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248643 |