

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2023

Submitted Date:

09/12/2023

Document Number:

712700648

**FIELD INSPECTION FORM**

Loc ID: 334176 Inspector Name: Pattillo, Curtis On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

21 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270583	WELL	PR	03/01/2019	CBM	067-08909	EMMA MCCARTY A 2	PR
284726	WELL	PR	11/18/2021	CBM	067-09160	EMMA MCCARTY A 4	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Locked gate, 2C40 key, off of neighborhood road.		
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Cfontents, volume labels, NFPA placard.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator and meterhouse have labels and NFPA placards.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	Posted on wellhead sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Land owner parking livestock trailers on edge of location.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Pipe fencing on two sides.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panel enclosure.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panel enclosure around separator, meterhouse, telemetry, and produced water tank.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Linear rod pump		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	3" line from separator to meterhouse. Calibration date 7/5/2023.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	3" line from wellhead to separator.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Eletrical service panel and boxes.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Cathodic protection		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical transformer		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.209040,-107.626260
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Inspector Name: Pattillo, Curtis

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Wells Served By Facilities Above**

**AirsID**

API Number
067-08909

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Culverts	Pass			
Berms	Pass					
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel				

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700652	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248990">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248990</a>