

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/14/2023

Submitted Date:

09/14/2023

Document Number:

702402347

FIELD INSPECTION FORM
 Loc ID 333171 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Grabber, Nikki		nikki.graber@state.co.us	
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241909	WELL	SI	11/01/2022	OW	123-09700	MOSER 1-A	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	OTHER	
Comment:	Mechanical issue WH leaking	
Corrective Action:	Comply with Rule 608	Date: 08/26/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	WELLHEAD	
Comment:	Temporary orange construction fencing around the excavation around the WH	
Corrective Action:		Date:

Equipment:		corrective date
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 241909 Type: WELL API Number: 123-09700 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 06/30/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.027630 Long: -104.850490Wind: Light Speed: 1-3 (mph) Direction From: NE Weather: Mostly Temperature: 70 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
01:53	PM	01:53	PM	Wellhead(s)

Comment: There are ladders in the excavation where they attempted to isolate the leak but the well is still leaking.Corrective Action: Comply with Rule 608Date: 08/26/2023**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 9-14-2023 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 702402278 for Mechanical Issue 608 only.</p> <p>Operator: KP Kauffman</p> <p>Location name: Moser 1-A</p> <p>API #05-123-09700</p> <p>County: Weld</p> <p>Weather: Cloudy.</p> <p>Location: dry.</p> <p>While there, I observed a wellsite and tank battery, SI at the time of the inspection. During this inspection, I observed the following possible compliance issue has not been addressed and is delinquent:</p> <p>608 Mechanical Issue: CA date 8-26-2023.</p> <p>See attached photos and video.</p> <p>I spoke with Mani Silva KP Kauffman Supervisor at approximately 1420 hrs. about the WH still leaking. He said they have tightened it as best that they can and are working to get a workover rig on the well.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	09/14/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402348	FLIR reinspection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6251394
702402349	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6251395