

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2023

Submitted Date:

09/08/2023

Document Number:

707800601

**FIELD INSPECTION FORM**

Loc ID 334080	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				<b>Findings:</b> 12 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270557	WELL	PR	12/01/2020	GW	045-09562	S.PARACHUTE TBI 36-34	PR
275592	WELL	PR	02/01/2021	GW	045-10353	TBI FEDERAL 31-5 (PI36)	PR
275594	WELL	PR	05/01/2023	GW	045-10355	TBI FEDERAL 31-12 (PI 36 -7-	PR
275595	WELL	PR	09/01/2020	GW	045-10356	TBI FEDERAL 31-13 PI36-7 -96	PR
275597	WELL	PR	05/01/2023	GW	045-10358	TBI FEDERAL 36-16 (PI 36 -7-	PR
283462	WELL	PR	02/01/2021	GW	045-11925	ENCANA FEDERAL 31-13BB (PI36)	PR
283525	WELL	PR	04/01/2023	GW	045-11931	ENCANA FEDERAL 36-16BB (PI36)	PR

**General Comment:**

ECMC Inspection Report Summary  
 On Monday 9/4/2023, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus PI 36, at Location # 334080 in Garfield county Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A (battery signage) has been completed.  
 During this inspection the following compliance issues were observed:  
 1. Chemical tank containment is full of fluid  
 Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Chemical tank containment is full of fluid		
Corrective Action:	Evacuate fluids in containments to provide adequate space in case of a spill		Date: 10/06/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 6		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	270557	Type:	WELL	API Number:	045-09562	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	275592	Type:	WELL	API Number:	045-10353	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	275594	Type:	WELL	API Number:	045-10355	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	275595	Type:	WELL	API Number:	045-10356	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	275597	Type:	WELL	API Number:	045-10358	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283462	Type:	WELL	API Number:	045-11925	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283525	Type:	WELL	API Number:	045-11931	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403525067	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246200">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246200</a>
707800607	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246195">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6246195</a>