

Inspection Photos
Location Name: Oxnard East 0607-8CH
Location ID: 452516



Photo 1 Location Sign



Photo 2 Oily waste around sump in northeast corner of secondary containment



Inspection Photos
Location Name: Oxnard East 0607-8CH
Location ID: 452516



Photo 3 Salt crystals along south side of secondary containment



Photo 4 Salt crystals along south side of secondary containment

Inspection Photos
Location Name: Oxnard East 0607-8CH
Location ID: 452516



Photo 5 Saline water and salt crystals in southwest corner of secondary containment



Photo 6 Bucket of crude oil at recycle pump in standing saline water in southwest corner of secondary containment

Inspection Photos
Location Name: Oxnard East 0607-8CH
Location ID: 452516



Photo 7 Evidence of blowdown onto ground in separator building



Photo 8 Evidence of blowdown at separator inside separator building

Inspection Photos
Location Name: Oxnard East 0607-8CH
Location ID: 452516



Photo 9 Leaking fittings inside separator building




Photo 10 oily waste around wellhead