

ERF? - Could not find operator → Dillon, pull file.
 (Not listed) historical

COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 075-05032		LEASE NAME: Nicholson 2	
LOCATION: NESE-30-6N-54W		OPERATOR: Hunter Carter Oil	
DATE: 12-14-95		INSPECTOR: Binkley	
Insp. Type: SR	Insp. Status: PA	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	well plugged, cement	
Pits (Reserve/Production) (Rule 902, 903, 904)	pump base and anchors on site.	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	overgrown in sagebrush/grassland	
Miscellaneous	Possible - Les Session, Merions Oil Co.	



CORRECTIVE ACTION REQUIRED: Remove cement base and anchors.

Date Corrective Action Required By: 1-30-96 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

