



Impacted soil has been removed and the staining has been cleaned on the pumping unit concrete pad













