

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 9421 From entrance to location



Photo # 9422 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 9423 Location




Photo # 9424 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



**Photo # 9425 Tank not properly labeled, missing required information**

**Photo # 9426 Secondary containment not sufficient to contain spilled or released materials**


## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



**Photo # 9427 Secondary containment not sufficient to contain spilled or released materials**



**Photo # 9431 Secondary containment not sufficient to contain spilled or released materials**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC JUHAN FEDERAL 1-35-6S-94W Pad

Location ID: 322298



Photo # 9441 PRV vent & rupture disc vent lack caps




Photo # 9442 PRV vent & rupture disc vent lack caps