

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2023

Submitted Date:

09/19/2023

Document Number:

699107380

**FIELD INSPECTION FORM**

Loc ID 317706 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10528  
Name of Operator: ARCH OIL & GAS LLC  
Address: 16400 DALLAS PARKWAY SUITE 305  
City: DALLAS State: TX Zip: 75248

**Findings:**

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
317706	LOCATION	AC			-	ELMER KAUFMAN-62N63W 18SWSE	SI

**General Comment:**

This is a follow up to prior inspection document #699106873. Overgrown vegetation has been removed. NFPA placard and capacity label have not been done. Operator sign is not current at the tank battery.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard appears to be weathered and needs to be replaced. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	10/27/2023
Type	BATTERY		
Comment:	Incorrect operator sign needs to be updated. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	10/27/2023
Type	TANK LABELS/PLACARDS		
Comment:	Pit is missing capacity label. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h	Date:	10/27/2023

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 317706 Type: LOCATION API Number: - Status: AC Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI Tank Battery

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      On Tuesday 9/19/23 at approximately 0946hrs I, Inspector Adam Burns, Conducted an on-site inspection at Elmer Kaufman-62N63W 18SWSE Tank Battery of KP Arch Oil &amp; Gas LLC.                      Location ID #317706 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Incorrect operator sign needs to be updated. Install sign to comply with Rule 605.g. With a Corrective Action date of 10/27/23                      Pit is missing capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 10/27/23                      NFPA placard appears to be weathered and needs to be replaced. Install sign to comply with Rule 605.h. With a Corrective Action date of 10/27/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	09/19/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107381	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255796">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255796</a>