

# Inspection Photos

Loc: 333761

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 9/18/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



Sep 18, 2023 at 1:49:17 PM

**Photo 1.** Facing northwest at the beginning of the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:333761 | Date: 9/18/2023



## Inspection Photos



**Photo 2.** Facing northwest along the access road. There is erosion at the red arrow that will require BMP's for stabilization..





## Inspection Photos



**Photo 3.** Facing northwest toward the location. There is an electric utility at red arrow.





## Inspection Photos



**Photo 4.** This electric utility at south side remains unsecured.





## Inspection Photos



**Photo 5.** Facing northwest toward the cut slope.





## Inspection Photos



**Photo 6.** Center of the location facing west toward the cut slope. There are signs of erosion along the cut slope which is not stabilized.





## Inspection Photos



**Photo 7.** Facing north along the fill slope. There are noxious weeds (Canada thistle) shown at red arrows that need to be controlled..





## Inspection Photos



**Photo 8.** Facing southwest toward the cut slope. There are signs of erosion along the cut slope which is not stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:333761 | Date: 9/18/2023



## Inspection Photos



**Photo 9.** Facing southeast toward the well pad location which was not recontoured.





## Inspection Photos



**Photo 10.** View of erosion occurring along the cut slope..

