

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2023

Submitted Date:

09/19/2023

Document Number:

705000439

FIELD INSPECTION FORM

Loc ID 336291 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270083	WELL	SI	05/01/2022	GW	123-21819	REYNOLDS 8-24	PA
336291	LOCATION	AC			-	REYNOLDS-63N68W 24SENE	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 270083 Type: WELL API Number: 123-21819 Status: SI Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (Reynolds 8-24); ECMC form 42 notice start of plugging operations doc #403440602 received on 06/21/2023. On location flowlines have been removed; ECMC form 42 notices of flowline abandonment (removal) completed doc #403526426 recieved on 09/11/2023. The facility/ tank battery is decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery have been removed. No flowlines/ risers observed on location. Fenced excavation observed on location at PA well. Remediation is in progress.

Corrective Action:

Date:

Facility ID: 336291 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403525813 received on 09/12/2023: On September 11, 2023, historically impacted soil was discovered during the removal of the flowline associated with the Reynolds 8-24 wellhead. Excavation and assessment activities are ongoing. Historically impacted soil was discovered during the removal of the flowline associated with the Reynolds 8-24 wellhead. Site infrastructure has been removed and will not be replaced.	maclarej	09/19/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000441	Wellhead excavation and signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256128
705000442	View of location; to NW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256129