

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2023

Submitted Date:

09/19/2023

Document Number:

705000440

FIELD INSPECTION FORM

 Loc ID 332203 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-
Findings:

3 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248584	WELL	SI		OW	123-16382	UPRC 9-9K	PA
271067	WELL	SI	05/01/2022	GW	123-21966	LUCKY L 9-23	PA
336580	LOCATION	AC			-	UPRC-63N66W 9NESE	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 248584 Type: WELL API Number: 123-16382 Status: SI Insp. Status: PA

Facility ID: 271067 Type: WELL API Number: 123-21966 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: (2) wells are plugged and abandoned (Lucky L 9-23, UPRC 9-9k); COGCC form 42 notices of start of plugging operations received June 2023. Off location flowlines between area (PA) wells and facility/ battery have been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery have been removed. ECMC form 42 notice of flowline abandonments (removal) completed doc #403534908 recieved on 09/19/2023. Fenced excavations observed at PA wells and tank battery/ equipment areas. Remediation work (historical) is in progress.

Corrective Action: _____ Date: _____

Facility ID: 336580 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403527352 received on 09/13/2023: On September 12, 2023, historically impacted soil was discovered following the removal of the flowline associated with the Lucky L 9-23 wellhead. Excavation and assessment activities are ongoing. Historically impacted soil was discovered during the removal of the flowline associated with the Lucky L 9-23 wellhead. Site infrastructure has been removed and will not be replaced.	maclarej	09/19/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000443	Wellhead excavation; view N to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256130
705000444	Fenced excavation at facility; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256131
705000445	Wellhead excavation; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256132