

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Access road to location



Removed tank battery

Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060



Wellhead sign illegible



Removed meter house and separator equipment

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Debris from 5/24/23



Debris from 9/19/23

**Crowheart Energy LLC
Pepler Fee Com 12-18
Location ID: 313060**



Debris from 5/24/23



Debris from 9/19/23

Crowheart Energy LLC
Pepler Fee Com 12-18
Location ID: 313060



Debris



Debris

**Crowheart Energy LLC
Pepler Fee Com 12-18
Location ID: 313060**



Debris



Anchor not securely marked

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**




Erosion. Sediment migration leaving location



Sediment migration entering location

**Crowheart Energy LLC
Pepler Fee Com 12-18
Location ID: 313060**



Location view from Southeast corner. Entrance to location.



Location view from Northeast corner.

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Location view from Northwest corner

Location view from Southwest corner