

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2023

Submitted Date:

09/19/2023

Document Number:

707601853

**FIELD INSPECTION FORM**Loc ID 421229 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email   | Comment         |
|--------------|-------|---|-----------------|
| ,            |       | dnr_cogccengineering@state.co.us                  |                 |
| ,            |       | rbucogccinspectionreports@chevron.onmicrosoft.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 421243      | WELL | TA     | 03/14/2017  | OW         | 123-32865 | WEST IRRIGATION USX AB 33-23 | PA          |

**General Comment:**

This is a PLUGGED & ABANDONED WELL inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations: Cementing: Cement-surface.

Battery: Inactive. Shut-down.

Inactive Battery SE corner GPS coordinates: 40.523567 / -104.554179

Well GPS coordinates: 40.526070 / -104.550530

**Location****Lease Road:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | Access   |       |  |
| comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

Overall Good: ☐**Signs/Marker:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | OTHER                                     |       |  |
| Comment:           | Jobsite entrance & safety signage posted. |       |  |
| Corrective Action: |   | Date: |  |
| Type               | WELLHEAD                                  |       |  |
| Comment:           |   |       |  |
| Corrective Action: |   | Date: |  |
| Type               | BATTERY                                   |       |  |
| Comment:           |   |       |  |
| Corrective Action: |   | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☐**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 421243 Type: WELL API Number: 123-32865 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: Axis Energy

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 2,617'-0'Cement Volume (sx): 364 sxsGood Return During Job: YESCement Type: Class "G" Neat 15.8#Comment:

Workover Contractor: Axis Energy Services, Inc. Rig #714.  
Cement Contractor: Axis Energy Services, Inc.

## Reference:

Form 6N on file. Notice of Intent to Abandon date: 07/14/2023. Approved.

Form 42 on file. Notice of MIRU. Start Date: 09/14/2023. Approved.

Form 42 on file. Notice of Plugging Operations. Start Date: 09/18/2023. Approved.

2023/09/19:

Plugging Operations: Cementing: Cement-surface.

2023/09/19: JSA attached as photo to this report.

IWP: 0 PSI / 0 PSI / 0 PSI

HELD PJSM. POOH TBG. RU WL, BAIL 2 SX CMT, , SET CIBP @

2,617', RD WL. RIH W/ WS. RU CMTRS, PUMP 10 SX CMT, RD

CMTRS. PU, REV CIRC, POOH. BUBBLE TEST, PASSED. RU WL,

PERF @ 895', RD WL. CIRC MIN 86 BBL. RU CMTRS, PUMP 352 SX

CMT TO SURF, RD CMTRS. ND BOP, NU WH. RR AND RD. SDFN.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           | Pass            |                         |                       | Material Handling And Spill Prevention | Pass                     |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p>CECMC Inspection Report Summary:</p> <p>On TUE 09/19/2023 at approximately 14:05 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: NOBLE ENERGY INC<br/> Location Name: WEST IRRIGATION USX AB/33-23<br/> Location ID: 421229<br/> Well Name(s):<br/> West Irrigation USX AB 33-23.<br/> API: 123-32865.<br/> Location County: Weld County, Colorado<br/> Weather: Mostly Cloudy, dry.</p> <p>While there, I observed:<br/> Well(s): 1: Plugged &amp; Abandoned   PA.<br/> Plugging Operations: Cementing: Cement-surface.<br/> Battery: Inactive. Shut-down.<br/> Inactive Battery SE corner GPS coordinates: 40.523567 / -104.554179<br/> Well GPS coordinates: 40.526070 / -104.550530</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 09/19/2023 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description   | URL   |
|--------------|---------------|---|
| 707601854    | Site photo(s) | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256557">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256557</a> |