

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2023

Submitted Date:

09/20/2023

Document Number:

697602164

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Ahmadian, Alexander 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Anderson, Laurel		laurel.anderson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478542	SPILL OR RELEASE	CL	02/11/2022		-	Cosslet A 9 Flowline	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 478542/Remediation 18952. Any corrective actions from previous inspections that have not been addressed are still applicable. Contract environmental personnel was on location to perform quarterly groundwater monitoring at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Spill Discovery Date: 11/11/2020

Days open: 1,043 days

Current site status: Excavation open and fenced with cattle panel. Staining visible within excavation. Monitoring wells have been installed and free product was observed in one monitoring well.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment:

Very high weeds are growing within and around the remedial excavation.

Corrective Action:

Comply with Rule 606.

Date: 09/27/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

OTHER

Comment:

Metal fencing around the excavation is adequate.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spill/Remediation:**

Comment: Staining was still observed within the excavation. Excavation remains unchanged since the last inspection.
Free product was observed in one monitoring well during the quarterly groundwater monitoring event.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: 11/11/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Casing around the monitoring well is rusted and the cap has rusted off from at least one monitoring well	ahmadiiaa	09/20/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602165	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6257279