

Final Reclamation and Stormwater Inspection

Date: 09/18/2023

Operator: MAGPIE OPERATING INC - 52530

Location ID: 312143

Inspection Document #: 708200559

Logan County, CO

SESE Section 30 T8N R53W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 1. Taken at the location's entrance. Photo illustrates excavation operations (digging and hauling) of the former pit area.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 2. Taken from the southeast corner of the former pit. Photo illustrates excavation operations of E&P waste occurring over the former pit. Onsite Operator representative informed Staff that the waste was being sent to Washington County Landfill for disposal.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 3. Taken from the southwest corner of the pit; see comments in Photo 2.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 4. Taken from the center portion of the former pit; see comments in Photo 2.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 5. Stained soils observed on the western portion of the former production area. Staff first observed the stained soil on 08/03/2023 (doc #708200446); Operator submitted FIRR (doc #403526856) stating that all hydrocarbon impacted material was removed from the location and indicated that the corrective action was completed on 01/12/2023. Based on field observations during this inspection, the corrective action has not been completed. Manure pile pictured in the background (highlighted with green arrow).

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 6. Taken north of the former production areas. Photo illustrates that road base/gravel remains throughout the northern portion of the production areas and along the former access road to the wellhead. Final reclamation activities are required.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 7. Taken halfway between the former production areas and the wellhead location. See comments in Photo 6.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 8. Taken from the southern portion of the former wellhead location. Road Base and gravel remain throughout and the location will need to be leveled and/or graded to reflect pre-disturbance topography.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 9. Taken from the northern portion of the former wellhead location. During this inspection, Staff observed debris located throughout the former location. Debris was placed in a pile for removal.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 10. Taken from the former wellhead location. Roofing shingle debris was observed throughout and will need to be removed.

Inspection Photos
Location Name: Warnecke 1
Location ID: 312143



Photo 11. Facing east from the former wellhead location. See comments in Photo 6.