

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2023

Submitted Date:

09/20/2023

Document Number:

708901720

**FIELD INSPECTION FORM**

Loc ID 324097 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456945	Domestic Tap	AC	08/28/2018		-	Domestic Tap 29SESE	AC

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 09/20/2023 at approximately 11:08 hours, I, Compliance Specialist, Wayne Smelser Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 29SESE Location # 324097 in Garfield County Colorado.  
While there, I observed the domestic tap is derived from TEP sales line.  
  
[This is a summary of inspection report](#)

<b>Location</b>				
<b>Lease Road:</b>				
	Type Access			
	comment:			
	Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>				
<b>Emergency Contact Number:</b>				
	Comment:	<input style="width: 80%;" type="text"/>		
	Corrective Action:	<input style="width: 80%;" type="text"/>		
Date: _____				
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 80%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type OTHER			
	Comment:	Hog panels around Domestic tap		
	Corrective Action:			Date:
<b>Equipment:</b>				
				corrective date
Type: Other		# 1		
	Comment:	Domestic tap		
	Corrective Action:			Date:
<b>Venting:</b>				
	Yes/No	NO		
	Comment:			
	Corrective Action:			Date:
<b>Flaring:</b>				
Type				
	Comment:			
	Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 456945 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: While there, I observed the domestic tap is derived from TEP sales line. The pressure is regulated by a big Joe regulator. Following the regulator there is a fluid knock out with a PRV on it followed by another regulator & then an in line odorizer. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						
Gravel						Sparse
		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Domestic tap inspection only</a>	smelserw	09/20/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901721	Inspection 708901720 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6258815">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6258815</a>