

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2023

Submitted Date:

09/21/2023

Document Number:

693806460

FIELD INSPECTION FORM

Loc ID 314569 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10779
Name of Operator: SCOUT ENERGY MANAGEMENT LLC
Address: 13800 MONTFORT DRIVE SUITE 100
City: DALLAS State: TX Zip: 75240

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Morgan, John		john.morgan@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Johnson, Mike	972-674-8679	Mike.Johnson@scoutep.com	Regional Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229063	WELL	SI	05/10/2023	ERIW	103-06141	FEE 43	SI

General Comment:

UIC-MIT. Verification of repairs. Wellhead inspection only.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:
	Type Main		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 970-675-3700		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment: WAG skid			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
	Yes/No NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 229063 Type: WELL API Number: 103-06141 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>WEBR</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>05/04/2018</u>
			AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: 0 Csg psi: 1340 BH psi: 0

Insp. Status: Pass

Comment: UIC-MIT. Verification of repairs. Wellhead inspection only.
Ran 5 1/2" line from 5801' to sfc. Cemented with 283 sx 13.5# class G cmt.
Form 42 Doc#403530040 received 9/14/2023, with test scheduled for 9/25/2023.
Test date moved to 9/20/2023 at operators request.
Pressure well to 1340 psi. Hold for 15 min. Final pressure 1320 psi. -20 psi loss. OK
Test witnessed by COGCC using chart on test truck.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693806468	Inspection photos 9/20/2023	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6259639