

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
BROWN 35HZ/WARREN 12-35 FACILITY	N/A	Armando Munoz	8/23/2023

Work Summary	Reclamation Type	Land Use
Removed and windrowed carcasses from equipment and mowed them also did erosion repair on tank battery pad. Mowed surrounding areas of tank battery.	Stormwater	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	Yes	Location(s): BROWN_13C-26HZ Notes: Remove and windrow weed carcasses from equipment on site. Erosion repair on tank battery pad. Remove trash while removing weed carcasses. Mow area surrounding tank battery.

COMPLETION DETAILS

Total Area Affected: **0.13 acres**
Seed Mix: **None used**
Crop Type:
Soil Type: **Clay Loam**
Stabilization Date: **8/23/2023**
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

LOCATION INFO

Location(s) – Name: BROWN_13C-26HZ

COGCC ID: **336245**

Well APIs at Location: **12321641 12327153 12335156 12335157 12335160 12335163**

Land Rep:

Land Owner: **Cannon Land Co**

Rec Contractor PO(s): **M&E -**

Vendor PO(s):

Billing Notes: **DJ-L0016**

Legal Address: **(WELD) SWSW 35 3N66W**

Topsoil Source:

Variance Notes:

Private Utility Notes:

Wildlife Restrictions:

General Notes:

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: B2

Description:



Photo Name: B3

Description:



Photo Name: B4

Description:



Photo Name: B5

Description:

