

Inspection Photos

9/19/2023

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335647

Inspection No: 696205263

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 1: Photos taken from the north end of the Working Pad Surface. Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 3: Photo shows conductors on Location.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 4: Photo 4-6 taken from the topsoil stockpiles on the north and east end of the Location. Photos examples showing BMPs (hydromulch) has not been installed or maintained in accordance with good engineering practices, in accordance with Rules 1002.c and 1002.f



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 6: Photos taken from the topsoil stockpile on the south end of the Location, facing southwest/west. Operator has implemented hydromulch in conjunction with an erosion log to protect the stockpile from wind/water erosion, weeds, and to minimize sediment transport. BMPs appeared to be in proper functioning condition at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 7: Photo taken from the northern perimeter of the Location's disturbance area. Photo shows Operator has implemented an erosion log to minimize off-site sediment transport in conjunction with hydromulch.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



September 19, 2023

Photo 8: Photo taken from the northwest end of the Location (toe of the fill slope) facing southwest. Photo shows ditch has not been constructed in accordance with good engineering practices; ditch lacks a defined channel and is unconsolidated soils that will contribute to sediment-laden stormwater discharge.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335647



Photo 9: Photo taken from the west end of the Location, facing south. Photo shows sediment trap installed at the toe of the fill slopes. BMP has not been constructed in accordance with good engineering practices; BMP is inadequate in size and has not been constructed with a properly engineered outlet.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources