

Inspection Photos

Location Name: MUSTANG RESOURCES LLC DOWNING 24-22-6S-94W Pad

Location ID: 323818



Photo # 500 From entrance to location



Photo # 501 Location



Inspection Photos

Location Name: MUSTANG RESOURCES LLC DOWNING 24-22-6S-94W Pad

Location ID: 323818




Photo # 502 Location




Photo # 503 Wellhead sign laying on the ground/not conspicuously located